

LMS Service Report

Site Name: Lower Longwood Lake

Date: 5/14/2024

Signature:

Email: ggslockett@gmail.com, fishonforty@yahoo.com, longwoodlakecabinoowners@gmail.com

Description of Work

Waterbody

Lower Longwood Lake

Secchi (feet)

6

Dissolved Oxygen (ppm)

10

Posted Water Use Rescriptions

Temp(F)

64

PH

6.3

Hardness

90

☒ Yes ☐ No

Type of Service

☐ Survey ☒ Treatment ☐ Fountain Service ☐ WQ Sample Service ☐ Other Service

Species Treated

Curly Leaf Pondweed

Comments

Surveyed the lake, observed minor growth of Curly Leaf Pondweed on lower half of the lake. Treated the targeted vegetation with an aquatic herbicide to control the growth.

Past treatment for upper half of the lake is working well. Targeted vegetation is decomposing and being controlled.

L.M.S will return for further management.

Aquatic Algae Present

Aquatic Plants Present

Curly Leaf Pondweed

Service Image



LMS Service Report

Site Name: Lower Longwood Lake

Date: 5/14/2024

Signature:

Email: ggslockett@gmail.com, fishonforty@yahoo.com, longwoodlakecabinoowners@gmail.com

Observed Aquatic Plants & Algae
--



Curly Leaf Pondweed