

## LMS Service Report

Site Name: Lower Longwood Lake

Date: 4/19/2023

Signature:

Email: [ggslockett@gmail.com](mailto:ggslockett@gmail.com), [fishonforty@yahoo.com](mailto:fishonforty@yahoo.com), [longwoodlakecabinowners@gmail.com](mailto:longwoodlakecabinowners@gmail.com)

### Description of Work

Waterbody Lower Longwood Lake

Secchi (feet) 5 Dissolved Oxygen (ppm) 10 Posted Water Use Restrictions

Temp(F) 58 PH 6.6 Hardness 90  Yes  No

Type of Service  Survey  Treatment  Fountain Service  WQ Sample Service  Other Service

Species Treated

### Comments

Arrived at site for Spring Surveyed, observed minor growth of Curly Leaf pondweed. No treatment is required at this time. Initial treatment will be applied within the next month.

Overall condition of the lake is good.

L.M.S will return for further management.

### Aquatic Algae Present

### Aquatic Plants Present

Curly Leaf Pondweed

### Service Image



## LMS Service Report

Site Name: Lower Longwood Lake

Date: 4/19/2023

Signature:

Email: [ggslockett@gmail.com](mailto:ggslockett@gmail.com), [fishonforty@yahoo.com](mailto:fishonforty@yahoo.com), [longwoodlakecabinowners@gmail.com](mailto:longwoodlakecabinowners@gmail.com)

### Observed Aquatic Plants & Algae



Curly Leaf Pondweed