

Service Report

Site Name: Lower Longwood Lake

Date: 5/30/2018

Signature:

Email: nesesqpc@aol.com,
fishonforty@yahoo.com

Description of Work			
Waterbody	Lower Longwood Lake		
Secchi (feet)	6	Dissolved Oxygen (ppm)	9
Temp(F)	79	PH	6
Hardness	80	Posted Water Use Resctrictions	
Type of Service		<input type="checkbox"/> Survey <input checked="" type="checkbox"/> Treatment <input type="checkbox"/> Fountain Service <input type="checkbox"/> WQ Sample Service <input type="checkbox"/> Other Service	
Species Treated Eurasian Milfoil, Filamentous			
Comments Surveyed the targeted treatment areas, Observed the moderate growth of Curly Leaf Pondweed and Eurasian Water Milfoil. Applied aquatic control products to manage the nuisance plant growth and the nuisance filamentous algae growth. Posted the property. AT will return for further management		Aquatic Algae Present Filamentous	
		Aquatic Plants Present Curly Leaf Pondweed Eurasian Milfoil	
Service Image			

Service Report

Site Name: Lower Longwood Lake

Signature:

Date: 5/30/2018

Email: nesesqpc@aol.com,
fishonforty@yahoo.com

Observed Aquatic Plants & Algae



Myriophyllum Spicatum



Potamogeton Crispus



Filamentous algae