

Service Report

Site Name: Lower Longwood Lake

Signature:

Date: 5/1/2019

Email: nesesqpc@aol.com, fishonforty@yahoo.com

Description of Work

Waterbody Lower Longwood Lake

Secchi (feet) 5 **Dissolved Oxygen (ppm)** 10 **Posted Water Use Resctrictions**

Temp(F) 64 **PH** 6 **Hardness** 60 Yes N

Type of Service Survey Treatmen Fountain WQ Sample Other Service

Species Treated

Comments

Surveyed the Upper Middle and Lower Reservoirs. Observed the minor gro
wth of Curly-Leaf Pondweed and Eurasian Water Milfoil.

Treatment not required at this time

Lake volume is high due to recent rain.

Spoke with resident near eastern cove concerning management

AT will return at a later date

Overall Quality: Very Good

Aquatic Algae Present

Aquatic Plants Present

Curly Leaf Pondweed
Eurasian Milfoil
Spaddderdock
Water Lily

Service Image

Service Report

Site Name: Lower Longwood Lake

Signature:

Date: 5/1/2019

Email: nesesqpc@aol.com, fishonforty@yahoo.com

Observed Aquatic Plants & Algae



Myriophyllum Spicatum



Potamogeton Crispus



Nuphar spp.



Nymphaea spp.