

## Service Report

Site Name: Lower Longwood Lake

Date: 6/7/2019

Signature:

Email: [nesesqpc@aol.com](mailto:nesesqpc@aol.com), [fishonforty@yahoo.com](mailto:fishonforty@yahoo.com), [longwoodlakecabinowners@gmail.com](mailto:longwoodlakecabinowners@gmail.com)

### **Description of Work**

Waterbody Lower Longwood Lake

Secchi (feet) 6 Dissolved Oxygen (ppm) 9 Posted Water Use Restrictions

Temp(F) 74 PH Hardness  Yes  No

Type of Service  Survey  Treatment  Fountain Service  WQ Sample Service  Other Service

Species Treated

### Comments

Pre-Treatment Survey: Surveyed the treatment area, observed the growth of your Eurasian Water Milfoil and Curly-Leaf Pondweed.

AT will return within the next 7 to 10 days to complete initial treatment for control of aquatic vegetation.

Overall condition: good.

Spoke with Jeff, Mike and Gary concerning management.

### **Aquatic Algae Present**

### **Aquatic Plants Present**

Curly Leaf Pondweed  
Eurasian Milfoil

### **Service Image**

## Service Report

Site Name: Lower Longwood Lake

Date: 6/7/2019

Signature:

Email: [nesesqpc@aol.com](mailto:nesesqpc@aol.com), [fishonforty@yahoo.com](mailto:fishonforty@yahoo.com), [longwoodlakecabinowners@gmail.com](mailto:longwoodlakecabinowners@gmail.com)

### **Observed Aquatic Plants & Algae**



Eurasian Milfoil



Curly Leaf Pondweed