

Service Report

Site Name: Lower Longwood Lake

Signature:

Date: 6/14/2019

Email: nesesqpc@aol.com, fishonforty@yahoo.com, longwoodlakecabinowners@gmail.com

Description of Work

Waterbody	Lower Longwood Lake			
Secchi (feet)	9	Dissolved Oxygen (ppm)	9	Posted Water Use Restrictions
Temp(F)	74	PH	6	Hardness 80 <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Type of Service	<input type="checkbox"/> Survey <input checked="" type="checkbox"/> Treatment <input type="checkbox"/> Fountain Service <input type="checkbox"/> WQ Sample Service <input type="checkbox"/> Other Service			
Species Treated	Eurasian Milfoil, Filamentous			

Comments

Surveyed the lake: observed the growth of Curly Leaf Pondweed and Eurasian Water Milfoil along the shoreline and Cove areas. Applied aquatic products to control the targeted vegetation throughout entire treatment area.

Observed the minor growth filamentous algae within the weed beds. Applied algaecides for the control of the target populations.

Overall condition: very good

AT will return for further management.

Aquatic Algae Present

Filamentous

Aquatic Plants Present

Bladderwort
Eurasian Milfoil
Curly Leaf Pondweed
Clasping-Leaf Pondweed
Bushy Pondweed
Large-Leaf Pondweed
Lyngbya
Narrow Leaf Pondweed
Phragmites
Sago Pondweed
Spadederdock
Vallisneria

Service Image

Service Report

Site Name: Lower Longwood Lake

Signature:

Date: 6/14/2019

Email: nesesqpc@aol.com, fishonforty@yahoo.com, longwoodlakecabinowners@gmail.com

Observed Aquatic Plants & Algae



Narrow Leaf Pondweed



Eurasian Milfoil



Sago Pondweed



Bladderwort



Curly Leaf Pondweed



Phragmites



Spatterdock



Filamentous



Watershield