

Service Report

Site Name: Lower Longwood Lake

Date: 8/6/2020

Signature:

Email: ggslockett@gmail.com, fishonforty@yahoo.com, longwoodlakecabinowners@gmail.com

Description of Work

Waterbody	Lower Longwood Lake			
Secchi (feet)	5	Dissolved Oxygen (ppm)	7	Posted Water Use Restrictions
Temp(F)	84	PH	7	Hardness 100 <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Type of Service	<input type="checkbox"/> Survey <input checked="" type="checkbox"/> Treatment <input type="checkbox"/> Fountain Service <input type="checkbox"/> WQ Sample Service <input type="checkbox"/> Other Service			
Species Treated	Lyngbya, Water Lily			

Comments

Surveyed the lake. Observed minor growth of Lyngbya along the power lines and cove cabin. Applied algaecide to control the growth of targeted nuisance algae in these areas.

Also treated Water Lillie's as requested by homeowner on Yellow Road. Past treatments are working well. Plants are continuing to decompose.

A T will return for further management.

Aquatic Algae Present

Aquatic Plants Present

Lyngbya

Service Image

Service Report

Site Name: Lower Longwood Lake

Date: 8/6/2020

Signature:

Email: ggslockett@gmail.com, fishonforty@yahoo.com, longwoodlakecabinowners@gmail.com

Observed Aquatic Plants & Algae



Lyngbya